


Sheaths

Main Features	
Description	brass sheaths to place thermometers and temper. sensors to measuring spots
Application	the sheaths protect sensors of thermometers and temperature probes, permitting their easy replacement if needed


Technical data	
Max. pressure	10 bar
Max. temperature	110 °C

Single-sensor sheath




Type	7x9-45	7x9-60	7x9-100	7x9-120	7x9-160	7x9-180	7x9-200
Dimension A [mm]	45	60	100	120	160	180	200
Weight [g]	60	65	75	80	85	90	95
Material	Brass CuZn40Pb3						
Code	14879	15746	14880	15745	16590	16591	14881

Three-sensor sheath



Type	15x17-100	15x17-130	15x17-220
Dimension A [mm]	100	130	222
Weight [g]	80	85	120
Material	Brass CuZn40Pb3		
Code	15744	16592	15743

Four-sensor sheath



Type	15x17-120
Dimension A [mm]	120
Weight [g]	70
Material	Brass CuZn40Pb3
Code	14882